	Approved For Release 2002/07/22: CIA-RDP8	T 25X1A
DUSTRY.	CENTRAL INTELLIGENCE AGE	
COUNTRY	East Germany	DATE DISTR: 22 Se tember 1953
SUBJECT	Condition of East Garmen Coal Mines	NO. OF PAGES
PLACE ACQUIRED		NO. OF ENCLS.
DATE OF		SUPPLEMENT TO REPORT NO
	25X1A	
OF THE BUILD !	IR ART SARREN TO ARE DESCRIPTION OF THE TOTAL THE ROTTER OF THE POST IS TOTAL THE POST IS TO THE	S IS UNEVALUATED INFORMATION
SOURCE.	25X1X	

- Lamp of the coal mine shafts of Last German coal mines are becoming unfit to work in, due to the dangerous conditions resulting from insufficient or faulty shoring timbers and supports. This situation has been impercible for some time and is only now becoming critical. Lany attempts have been impercible to obtain the necessary materials through wast-sort trade, since teap are analyzed in wast Germany; recently an attempt was made to obtain pitch line from the L. S. through the Luiss firm of Eximport.
- 2. In the Steinkehlenberghau in Zwickau, the inspecting safety commission recently refused to certify most of the shafts as safe, and the workers refuse to enter many of the shafts. In all the coal mines of wast (enterly, an estimated one-third of the shafts are not being worked because of medical of the miners to work in them.

CLASS	SIFICATION: SECRET		, ja 154	25X1A
	ISRB DISTR	IBUTION	OIT Z	· · · · · ·
MIN #X AIR FX F	81			